

Annexure D

BUILDING SAFETY CERTIFICATE

No. 57

Dated: 23/05/2026

It is certified that the existing building SABARMATI GYAN NIKETAN (name of the building or premises) at GANDHI NAGAR TELHARA, BLOCK-EKANGAR SARAY, NALANDA (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+1	—	—	—	—	—

The building is owned/occupied by SABARMATI GYAN NIKETAN (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of BUILDING CONS. DEPTT. (Name of Department/ Govt.) on 22/05/2026 (date of inspection) in the presence of Phai Suresh Prasad, SABARMATI GYAN NIKETAN, TELHARA (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 22/05/2026 for a period of 1 (ONE) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Building safe in Normal situation
2. —
3. —
4. —

Issued on 23/05/2026 at HILSA, NALANDA by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : [Signature]

Name : ASHUTOSH KUMAR

Designation : Assistant Engineer

Name & Address of Department/ Office: B.C.D HILSA, NALANDA, BIHAR